MIDDLETON RAILWAY TRUST RISK ASSESSMENT



		ASSESSMENT NO:	E17
ACTIVITY	Oxy-Gas Cutting and Welding		
LOCATION	Anywhere		

Tick Boxes Where Applicable

IDENTIFIABLE HAZARDS						
Electrical Noise Moving Parts Heat Fire or explosion Emission Chemical Fall Other (specify)	Rotation From Fluids Solid 🗸	Trapping From Solid ✓ Gas ✓	Striking From flame ✓ Liquid			
PERSONS AT RISK Sole Person 🗸	Persons nearby 🗸	Visitors	Others			
CONTROL MEASURES						
Guards Against Removal of Sources of Ig PPE	heat gnition ✓ Clear goggles Dust Mask	Moving parts Welding goggles Gloves	Emissions Ear defenders Helmet			
Notices	Other (specify)	Leather apron when neces				
Authorisation Required						

ADDITIONAL NOTES

- Flashback arrestors to be fitted
- Bottle keys to always be available
- Ensure fire extinguishers are close to hand
- Danger to others from careless handling of lighted blowpipe and do not put down lighted blowpipe
- Do not cut onto close concrete surfaces danger of concrete 'spitting'
- Danger from misuse of oxygen
- Do not use on tanks that have contained flammable fluids
- Remove all combustible materials and maintain 'fire watch' for one hour after work finished

ASSESSMENT CARRIED OUT BY:	S J Roberts
DATE:	26/1/01
REVIEWED:	01/03/15