MIDDLETON RAILWAY TRUST RISK ASSESSMENT



		ASSESSMENT NO:	E11
ACTIVITY	Use of Screw Cutting Machine		
LOCATION	Workshop		
Tick Boxes Where Applicable			
IDENTIFIABLE HAZARDS			
Electrical Noise Moving Parts Heat Fire or explosion Emission Chemical Fall Other (specify)	Rotation From Fluids Solid F	Trapping From Solid Gas	Striking From flame Liquid
PERSONS AT RIS Sole Person		Visitors	Others
CONTROL MEASURES			
Guards Against Removal of Source PPE Notices	heat s of Ignition Clear goggles V Dust Mask Other (specify) (Specify)	Moving parts Welding goggles Gloves	Emissions Ear defenders Helmet
Authorisation Required	✓		
Danger from sharp swarf cuttings. Care necessary when cleaning. ASSESSMENT CARRIED OUT DV. S.I. Poborts			
ASSESSMENT CARRIED OUT BY: S J Roberts			

DATE: 25/1/01 **REVIEWED:** 01/03/15