


MIDDLETON RAILWAY TRUST RISK ASSESSMENT



		ASSESSMENT NO:	E15
ACTIVITY	Painting		
LOCATION	Anywhere		

Tick Boxes Where Applicable

IDENTIFIABLE HAZARDS			
Electrical	<input type="checkbox"/>	Rotation	<input type="checkbox"/>
Noise	<input type="checkbox"/>	From Fluids	<input type="checkbox"/>
Moving Parts	<input type="checkbox"/>	Solid	<input type="checkbox"/>
Heat	<input type="checkbox"/>	Trapping	<input type="checkbox"/>
Fire or explosion	<input checked="" type="checkbox"/>	From Solid	<input type="checkbox"/>
Emission	<input checked="" type="checkbox"/>	Gas	<input type="checkbox"/>
Chemical	<input checked="" type="checkbox"/>	Liquid	<input checked="" type="checkbox"/>
Fall	<input checked="" type="checkbox"/>	Striking	<input type="checkbox"/>
Other (specify)	<input type="checkbox"/>	From flame	<input type="checkbox"/>

PERSONS AT RISK			
Sole Person	<input checked="" type="checkbox"/>	Persons nearby	<input checked="" type="checkbox"/>
Visitors	<input type="checkbox"/>	Others	<input type="checkbox"/>

CONTROL MEASURES			
Guards Against	heat	Moving parts	Emissions
Removal of Sources of Ignition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PPE	Clear goggles	Welding goggles	Ear defenders
	Dust Mask	Gloves	Helmet
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Notices	Other (specify)		
	(Specify)		
Authorisation Required	<input type="checkbox"/>		

ADDITIONAL NOTES
<ul style="list-style-type: none"> Possibility of paint splashes in eye, similarly when using thinners. (See COSHH Assessments) Dust from surface preparation (see COSHH Assessments) Use goggles and dust masks when necessary Danger of falling if working from a ladder – ensure ladder is adequately secured – do not lean. Provide somewhere for paint tin – do not hold.

ASSESSMENT CARRIED OUT BY:	S J Roberts
DATE:	26/1/01
REVIEWED:	01/03/15