MIDDLETON RAILWAY TRUST RISK ASSESSMENT



| | | ASSESSMENT NO: | E1 |
|----------|----------------|----------------|----|
| ACTIVITY | Use of Ladders | | |
| LOCATION | Anywhere | | |
| | | | |

Tick Boxes Where Applicable

| IDENTIFIABLE HAZARDS | | | | | |
|-------------------------|-----------------|-----------------|---------------|--|--|
| | 55 | | | | |
| Electrical | | | | | |
| Noise | | | | | |
| Moving Parts | Rotation | Trapping | Striking | | |
| Heat | From Fluids | From Solid | From flame | | |
| Fire or explosion | | | | | |
| Emission | Solid | Gas | Liquid | | |
| Chemical | | | | | |
| Fall 🗸 | | | | | |
| Other (specify) | | | | | |
| | | | | | |
| | | | | | |
| PERSONS AT RISK | | | | | |
| | | | | | |
| Sole Person 🗸 | Persons nearby | Visitors | Others | | |
| | | | | | |
| CONTROL MEASURES | | | | | |
| | | | | | |
| Guards Against | heat | Moving parts | Emissions | | |
| Removal of Sources of I | gnition | | | | |
| PPE | Clear goggles | Welding goggles | Ear defenders | | |
| | Dust Mask | Gloves | Helmet 🗸 | | |
| | Other (specify) | | | | |
| Notices | (Specify) | | | | |
| | | | | | |
| | | | | | |
| Authorisation | | | | | |
| Required | | | | | |

ADDITIONAL NOTES

- Ensure that ladder is 'footed' or securely tied
- Do not lean from ladder; always keep both feet on ladder and hold with one hand
- Do not use damaged ladders; always inspect before using
- Ensure ladder is 'in date'
- Consider alternative means of undertaking the task

| ASSESSMENT CARRIED OUT BY: | S J Roberts |
|----------------------------|-------------|
| DATE: | 25/1/01 |
| REVIEWED: | 01/03/15 |