


MIDDLETON RAILWAY TRUST RISK ASSESSMENT



		ASSESSMENT NO:	E29
ACTIVITY	Use of Router		
LOCATION	Anywhere		

Tick Boxes Where Applicable

IDENTIFIABLE HAZARDS			
Electrical	<input checked="" type="checkbox"/>	Rotation	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>	From Fluids	<input type="checkbox"/>
Moving Parts	<input checked="" type="checkbox"/>	Solid	<input checked="" type="checkbox"/>
Heat	<input type="checkbox"/>	Trapping	<input type="checkbox"/>
Fire or explosion	<input type="checkbox"/>	From Solid	<input type="checkbox"/>
Emission	<input checked="" type="checkbox"/>	Gas	<input type="checkbox"/>
Chemical	<input type="checkbox"/>	Liquid	<input type="checkbox"/>
Fall	<input type="checkbox"/>	Striking	<input type="checkbox"/>
Other (specify)	<input checked="" type="checkbox"/>	From flame	
Danger of kickback, both of machine and workpiece			

PERSONS AT RISK			
Sole Person	<input checked="" type="checkbox"/>	Persons nearby	<input checked="" type="checkbox"/>
Visitors	<input type="checkbox"/>	Others	<input type="checkbox"/>

CONTROL MEASURES			
Guards Against	heat	Moving parts	Emissions
Removal of Sources of Ignition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PPE	Clear goggles	Welding goggles	Ear defenders
	Dust Mask	Gloves	Helmet
Notices	Other (specify)		
	(Specify)		
Authorisation Required	<input checked="" type="checkbox"/>		

ADDITIONAL NOTES
<ul style="list-style-type: none"> • Ensure cutter is tight in collet before using • Ensure that cutter will not come into contact with supporting materials • Ensure cutter is up to speed before contacting workpiece • Ensure that power cables are kept well clear of cutter • Ensure that direction of cut is correct

ASSESSMENT CARRIED OUT BY:	S J Roberts
DATE:	18/8/14
REVIEWED:	