## MIDDLETON RAILWAY TRUST RISK ASSESSMENT



	Г	4005004545	- File	
A OTI) (IT) (	F1	ASSESSMENT NO	E16	
ACTIVITY	Electric Welding			
LOCATION	Workshop			
Tick Boxes Where Applicable				
IDENTIFIABLE HAZARDS				
Electrical Noise Moving Parts Heat Fire or explosion Emission Chemical Fall Other (specify)	Rotation From Fluids Solid ✓	Trapping From Solid ✓  Gas ✓	Striking	
Curor (opcomy)				
PERSONS AT RISI	K			
Sole Person	Persons nearby	Visitors	Others	
CONTROL MEASU	JRES			
Guards Against Removal of Source: PPE	s of Ignition Clear goggles Dust Mask	Moving parts  Welding goggles  Gloves	Emissions  Ear defenders  Helmet	
	Other (specify) ✓	Leather aprons may be appr		
Notices	(Specify)		1	
Authorisation Required	✓			
ADDITIONAL NOTES				

- Remove all local sources of ignition paint, thinners, rags, paper, paraffin, diesel, etc. Ensure fire extinguishers are at hand.
- Ensure workpiece is properly earthed.
- Take precautions to avoid others from receiving welding flashes
- Do not weld galvanised materials
- See COSHH Assessment for welding fumes
- Coded welders to be employed for pressure vessel or other critical work

ASSESSMENT CARRIED OUT BY:	S J Roberts
DATE:	26/1/01
REVIEWED:	01/03/15