


MIDDLETON RAILWAY TRUST RISK ASSESSMENT



		ASSESSMENT NO:	E25
ACTIVITY	Use of Table Saw		
LOCATION	Workshop		

Tick Boxes Where Applicable

IDENTIFIABLE HAZARDS			
Electrical	<input checked="" type="checkbox"/>	Rotation	<input checked="" type="checkbox"/>
Noise	<input type="checkbox"/>	From Fluids	<input type="checkbox"/>
Moving Parts	<input checked="" type="checkbox"/>	Solid	<input checked="" type="checkbox"/>
Heat	<input type="checkbox"/>	Trapping	<input type="checkbox"/>
Fire or explosion	<input type="checkbox"/>	From Solid	<input type="checkbox"/>
Emission	<input checked="" type="checkbox"/>	Gas	<input type="checkbox"/>
Chemical	<input type="checkbox"/>	Liquid	<input type="checkbox"/>
Fall	<input type="checkbox"/>	Striking	<input type="checkbox"/>
Other (specify)	<input type="checkbox"/>	From flame	<input type="checkbox"/>

PERSONS AT RISK			
Sole Person	<input checked="" type="checkbox"/>	Persons nearby	<input checked="" type="checkbox"/>
Visitors	<input type="checkbox"/>	Others	<input type="checkbox"/>

CONTROL MEASURES			
Guards Against	heat	Moving parts	Emissions
Removal of Sources of Ignition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PPE	Clear goggles	Welding goggles	Ear defenders
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Dust Mask	Gloves	Helmet
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notices	Other (specify)		
<input checked="" type="checkbox"/>	(Specify)		
Authorisation Required			
<input checked="" type="checkbox"/>			

ADDITIONAL NOTES
<ul style="list-style-type: none"> • Hands to be no closer to blade than 12"(300mm) . Use a push stick. • Ensure blade is at full speed before introducing workpiece • If guard has to be removed for angle or close cuts, replace immediately after use • Ensure that long lengths are adequately supported • Assistance required for large sheets

ASSESSMENT CARRIED OUT BY:	S Roberts
DATE:	18/8/14
REVIEWED:	